FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $7-17-73$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2504 SIZE OF PIPE USED $6''$	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 1/3 EAST OF 14 9 DEEP GURB LINE AND DEPTH 1/3 EAST OF 14 9 DEEP
WAS LATERAL AT GURB? PROP LINE WAS ATTACHED TO MAIN	NAME OF CONTRACTOR FRANKS
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	LL OF BUILDING SERVED.
	The second secon
en de la composition de la composition La composition de la	118' 19'DEEF
SIGNED William Hemme	FILED AT ENGINEER'S OFFICE
Inspector for City	

№ 8665

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

13

MASSILLON, OHIO, July 16
RECEIVED OF Lacies the agria, In. FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED FALLES SLEEDANCE DV.
TO TAP Jantary SEWER ON THE WITH
OF Tanglement Dr. 116. AVE. TYPE OF STREET Chip & See
THE PREMISES BEING LOT NO. 13586 , HOUSE NO. 2504
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND 1 OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR FLAMES

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.