FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8677 AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAI	NAME OF CONTRACTOR
~	30° × 70 30° × 70 430 × 90
SIGNED Inspector for City REMARKS	FILED AT ENGINEER'S OFFICE

№ 8677

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, August 17.
RECEIVED OF Nanavahy	FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED Paul	
TO TAP Santant SET	
of Tangleway On. V. E AVE. TY	
THE PREMISES BEING LOT NO. 13073	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
mile to	
NAME OF CONTRACTOR 11 WIRMLIE	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.