№ 8682

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-17-73	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1305	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 227 EAST OF M and 8'D CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR MAINVITE.	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	N 23' N 19' PROP. CHEB	
SIGNED William Hammer Inspector for City	FILED AT ENGINEER'S OFFICE	

Nº 8682

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, John .
RECEIVED OF H M. Ca	<i>I</i>
FOR WHICH PERMISSION IS GRANTED 11. 291	· /
TO TAP Sanitary SEV	7 1 1/1 -
OF Spinishel VIno. N. E AVE. TYL	•
THE PREMISES BEING LOT NO. 12860	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Malanite	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.