

19-21

Nº 8686

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9/26/73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

145'

HOUSE NO.

414

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8686

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 25*

RECEIVED OF *Earl Klisch*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Earl Klisch*

TO TAP *Sanitary*

SEWER ON THE *East*

OF *25th St. N.W.*

AVE.

ST. TYPE OF STREET *Chapman & Paul*

THE PREMISES BEING LOT NO. *15172*

HOUSE NO. *414*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Klisch*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**