№ 8689

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 10-17-73 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|-----------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|--|
| HOUSE NO. 2348 | DISTANCE FROM FIRST MANUALT | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH SO SO SO SO SO SO SO SO SO S | |
| WAS LATERAL AT-CURB? | Prop | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR M. GERTSENSLA GER | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| \mathcal{N} | PorcH | |
| | 704 5 | |
| | 15 8 DP | |
| SIGNED Jathon | FILED AT ENGINEER'S OFFICE | |
| Inspector for City | | |

№ 8689

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | MASSILLON, OHIO, Ut. 3 | |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------|--|
| RECEIVED OF Line We | alter FEE OF \$ 2. | |
| | Waltu. | |
| TO TAP Sanitary SE | WER ON THE MARKET | |
| OF Taughter 1/ 1/ AVE. TY | | |
| THE PREMISES BEING LOT NO. 13593 | * / | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. | | |
| NAME OF CONTRACTOR Succession | <u></u> | |
| Note: Whis manualt | . * T | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.