

N^o 8692

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-18-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

BEAVER CONST.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

L. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

THIS SEWER WAS PLUGGED IN BASEMENT CONNECTED TO CHURCH

207-0 2-10
Nº 8692

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct 15

RECEIVED OF Beaman Excavating FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED 8th St. Baptist Temple (Name)

CITY OF Santee TO-TAP Santee SEWER ON THE Street

OF 8th St. N.W. AVE. ST. TYPE OF STREET Main Street

THE PREMISES BEING LOT NO. 3629, HOUSE NO. 311

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beaman

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.