

19-

Nº 8693

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 10-18-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 250

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes


ACROSS FROM Mf

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

HOLDER BAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N

SIGNED

V. Sathorn

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8693

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Oct. 18*

RECEIVED OF

Halduburn

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED

Harold Kopp

TO TAP

Sanitary

SEWER ON THE

East

OF

21st St. N.W.

AVE.

ST. TYPE OF STREET

Chapel

THE PREMISES BEING LOT NO.

7221

HOUSE NO.

250

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Halduburn

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**