

5-12

N^o 8696

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
SIZE OF PIPE USED _____ CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House RAZED

10-26-73

DID NOT CUT OFF SEWER

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

Nº 8696

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Oct. 19

RECEIVED OF

Beaver Excavating

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED

Cut off Existing Sewer

TO TAP

SEWER ON THE

OF

Tremont Ave. S.E.

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

94-97

HOUSE NO.

800-802

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver Excavating

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.