## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED 5-25-24	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
	HOUSE NO.	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
<i>14</i>	WAS LATERAL AT CURB?	
	WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WA	
		/ Deep
	SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE

11' NOTH OF

Nº 8707

OF THE DEPARTMENT OF PUBLIC SERVICE.

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Man 3	/
RECEIVED OF Beau	B1 Ton	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Farina Redety Co.	
COT-0== Janutery	SEWER ON THE Mark	
or 1st ld. n. Tr.	AVE. ST. TYPE OF STREET	alexander of the second
THE PREMISES BEING LOT NO.		/
	, /ITH ORDINANCE NO. 19-1971 DULY PASSED BY THE (	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.