

No 8719

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-20-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

964

SIZE OF PIPE USED

4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?


Prop

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

4-9-74

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

House RAZED LATERAL CUT OFF

CUT-OFF

N^o 8719

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 7

RECEIVED OF Beamer Operating Co. FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED High City II

CUT-OFF Sanitary TO-TAP Sanitary SEWER ON THE East

OF Wals Rd. S.E. AVE. ST. TYPE OF STREET Hard Surface

THE PREMISES BEING LOT NO. 9641, HOUSE NO. 964

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beamer

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.