## ✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N^{\underline{o}}$ 8723 and signed when returned

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR
<del>.</del>	
the state of the s	$\phi_{ij}$ , $\phi_{ij}$ , $\phi_{ij}$ , $\phi_{ij}$ , $\phi_{ij}$ , $\phi_{ij}$
SIGNED	FILED AT ENGINEER'S OFFICE
BEMARKS DID NOT BLOS	ck Sewer

207 sast Nº 8723

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

m/ 19:

	MASSILLON, OHIO, 11 AMON 1	-1
768	RECEIVED OF Exhich Winching Co FEE OF \$ 5.	
601	FOR WHICH PERMISSION IS GRANTED Jones Bearly	
has had I	FOR WHICH PERMISSION IS GRANTED	
167 west	TO-TAP Sanday SEWER ON THE DESTA	
	of Turnent and S.E. ST. TYPE OF STREET Hard Ruylance	_
	THE PREMISES BEING LOT NO. 10 4 16, HOUSE NO	
e Transis de la companya de la compa	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.	)

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.