

N^o 8727

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-11-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 405

SIZE OF PIPE USED 4" 11'
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? IN CURB LINE

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED

[Signature]
Inspector for City

4-17-74

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
Nº 8727

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 5*

RECEIVED OF *Halderhausen*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Brown Lumber Co*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *Eric St. S.*

AVE.

ST. TYPE OF STREET *Hard Surface*

THE PREMISES BEING LOT NO. *D-1. 39*

HOUSE NO. *405*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Halderhausen*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**