**N**º ... 8746

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 123C	DISTANCE FROM FIRST MANHOLE DOWN STREAM  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH  DOWN STREAM TO DITCH AT
WAS LATERAL AT CURBY LINE YE	NAME OF CONTRACTOR G. HOLDER RAVM
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	
N - 1	1 141 12 7/2 12 45 9 5 11 P
SIGNED Inspector for City  REMARKS	FILED AT ENGINEER'S OFFICE 271

**№** 8746

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

RECEIVED OF AMAGENTAL MASSILLON, OHIO, 2/1/2	
FOR WHICH PERMISSION IS GRANTED And I American	
TO TAP Samtay SEWER ON THE	5. d
of Mudan had and S. W. AVE. TYPE OF STREET Charlet	the state of the s
THE PREMISES BEING LOT NO. 12930, HOUSE NO. 12	··· ***
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.