

N^o 8749

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

6-6-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1433

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
GURB LINE AND DEPTH

193' NORTH of MH 9'

WAS LATERAL AT CURB?

Yes



WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

R. FRANKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. V. Nathan

Inspector for City

193'

FILED AT ENGINEER'S OFFICE

REMARKS

