**№** -8755

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $G = 12 - 74$ HOUSE NO. $2112\overline{G}$ $212\overline{Z}$ SIZE OF PIPE USED $4'\overline{C}$ , $P$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	N 4'scr 20'
SIGNED Jalana La Inspector for City	- 28 - 7 4 FILED AT ENGINEER'S OFFICE
REMARKS	



**№** 8755

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO,	,
RECEIVED OF The Character Commence of the Comm	<u>.4</u>
FOR WHICH PERMISSION IS GRANTED TO TOUR TO TOUR TO THE TOUR TO THE TOUR TO THE TOUR TO THE TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOUR	
TO TAP Samutary SEWER ON THE MANTE	
OF March 1 C ST. TYPE OF STREET (165 1 Local)	
THE PREMISES BEING LOT NO. $110 + 316$ , HOUSE NO. $2112 - 2132$	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.