
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-12-24 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|--|--|
| HOUSE NO. 2/2 4 2/3 9 SIZE OF PIPE USED 9 6 1. P | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? | en de la companya de La companya de la co |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR BOGGEY |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL | OF BUILDING SERVED. |
| | CO 7 4'D - CP |
| | ofcip, o |
| SIGNED Inspector for City | 1-28-74 ILED AT ENGINEER'S OFFICE |
| REMARKS | |



OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

| | MASSILLON, OHIO, James 18 |
|---|----------------------------------|
| RECEIVED OF The Oslican C | FEE OF \$ 8.5 |
| FOR WHICH PERMISSION IS GRANTED TELESCOPE | a Estatu |
| TO TAB Sanctice I SEV | MER ON THE |
| OF HAISH HILL S. ST. TY | PE OF STREET CALL & Lac |
| THE PREMISES BEING LOT NO. $PUCH 326$ | B-2 , HOUSE NO. $21241-21341$ |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE. | |
| NAME OF CONTRACTOR PAGE | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.