

## Nº 8759 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-13-74                     | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |       |
|--|---|-------|
| HOUSE NO. 2172 70 3186                     | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT   |       |
|  | CURB LINE AND DEPTH                                   |       |
| WAS LATERAL AT CURB?                       |   |       |
| WAS ATTACHED TO MAIN                       | NAME OF CONTRACTOR BOTH                               |       |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL | L OF BUILDING SERVED.                                 |       |
|  | 31  |       |
| N  | 50 74'0,0   |       |
|  | 5.0   | 127   |
| / `  |   |       |
|  |   |       |
|  |   | :<br> |
|  |   | 1     |
| SIGNED 12 Tatham 6-                        | 27-74 FILED AT ENGINEER'S OFFICE                      |       |
| Inspector for City                         |   |       |
| REMARKS                                    |   | ·     |



## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER



Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.