

✓
N^o 8762

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

8-28-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Beaver

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

[Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

1500 1500
1489 1412

CIT-055

Nº 8762

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

62' NORTH OF
NH

139' NORTH OF
NH

MASSILLON, OHIO, June 19

RECEIVED OF Beane & Son

FEE OF \$ 5

FOR WHICH PERMISSION IS GRANTED Sanitary

TO TAP Sanitary

SEWER ON THE West

OF Churchland St.

AVE.
ST. TYPE OF STREET Churchland

THE PREMISES BEING LOT NO. 4177

HOUSE NO. 927

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Beane

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.