Nº 8776 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-30-34	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED WAS LATERAL AT CURB?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 70 5007 H 0 P M 7 P
WAS LATERAL AT CURB?	Prop
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR WEAVER
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	760
	36' \ 8'D
SIGNED Jackann Inspector for City	FILED AT ENGINEER'S OFFICE 70
REMARKS	

Nº 8776

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

RECEIVED OF	MASSILLON, OHIO, 30 , 19
FOR WHICH PERMISSION IS GRANTED	Mesone of James
OF AVE. ST.	
THE PREMISES BEING LOT NO. 12/1/11	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.