

N^o 8782

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-5-74

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

OAK

HOUSE NO. 41-63

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

PROP. LINE AT SOUTH AVE S. E
NORTH 135' 9" D

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

HOLDERBAYM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



PRELAY



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
N^o 8782

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Aug 20*

RECEIVED OF *Haldubauer*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *C. R. Adke (Capt.)*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Forest Ave S.E.*

AVE.
ST. TYPE OF STREET

Hardy Square

THE PREMISES BEING LOT NO. *326*

HOUSE NO. *41-63*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldubauer*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**