Nº 8783 → FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1 1 - 25 - 74	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·	
HOUSE NO. 335	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	UNP	
WAS LATERAL AT CURB? CUT OFF			
WAS ATTACHED TO MAIN			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
$\lambda$	7 60		
1	30		
	and the second s	<del>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</del>	
į.	all and the state of the state		
•			
SIGNED FILED AT ENGINEER'S OFFICE			
Inspector for City			
REMARKS			

59 WEST OF MH.

Cut - H

**№** 8783

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, August 18		
RECEIVED OF Study Luna	<u> </u>		
FOR WHICH PERMISSION IS GRANTED AND AND AND AND AND AND AND AND AND AN	Lumphi .		
Cont of January SE	WER ON THE Months		
OF Heolland C ST. TY			
The premises being lot no. $9391$			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR BURNING			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.