

N^o 8800

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

1-9-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

407

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

YES

WAS ATTACHED TO MAIN


NO

NAME OF CONTRACTOR

G. HOLDERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

8800
N^o 8800

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *December 10*

RECEIVED OF *Kalichman*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Access to sewer line*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *11 E*

AVE.

ST. TYPE OF STREET *Howard Avenue*

THE PREMISES BEING LOT NO. *226*

HOUSE NO. *207*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Kalichman*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**