Nº 8806

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $1-3-75$ HOUSE NO. $227$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? TO P	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR East 30 Eyes
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
	4.00
	0AK 51.5W
	<del>- 67 -</del>
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

**№** 8806

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, Lee 27
RECEIVED OF 6 1 30 1 100	FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED 1114 B	le Newman
CUX-UFF Janutary SE	
of Jak am J. W. AVE. T.	
THE PREMISES BEING LOT NO. $2/24$	· · · · · · · · · · · · · · · · · · ·
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR 6 BO 6 / Contract	ing Co.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.