Nº 8815 <sup>v</sup>

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $1-29-75^-$	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 3/6 SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? Prop,		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 13 EAUER CONST.	_~~-
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.	
CEN	Ter of LLey EAST OF ZINS O	
SIGNED L. Lattam	FILED AT ENGINEER'S OFFICE	
Inspector for City		
REMARKS		

CUTIFFE

## Nº 8815

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Jan. 27		
RECEIVED OF Binney Edin	etay 14 FEE OF \$ 5		
FOR WHICH PERMISSION IS GRANTED LEADING DOLLAR DESCRIPTION OF THE STATE OF THE STAT			
TO-TAP- Sanday si			
OF			
THE PREMISES BEING LOT NO. 1088	, HOUSE NO. 316		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.