√ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8817 AND SIGNED WHEN RETURNED

DATE INSPECTED 2-6-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 433	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH.
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 22 50 Sylve
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.

SIGNED		FILED AT ENGINEER'S	OFFICE
e de la companya de l	Inspector for City		
REMARKS AN NO	丁 ナノルロ	LATERAL	DUG HCROSS

№ 8817

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

massillon, ohio, Jan. 30

RECEIVED OF East 30 Cheanating FEE OF \$ 5. THE PREMISES BEING LOT NO. 2026, HOUSE NO. WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR Cart 30 Charactery

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

Flance muits to laceth H. Main 9 dep 1 at . 7' 2 at encles