

N^o 8819

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-20-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Repair

HOUSE NO.

114

SIZE OF PIPE USED

4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

Yes


WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

G. HOLDERBAUGH

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



EAST CURB

2-BRMS

6 1/2' DEEP

1' 0" 51

SIDEWALK

3'

SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

REPAIR

N^o 8819

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 20

RECEIVED OF Hildner FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Joe Carval

TO TAP Sanitary SEWER ON THE East

OF to 6th St. 71-E. AVE. ST. TYPE OF STREET Plank

THE PREMISES BEING LOT NO. 566, HOUSE NO. 114

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Hildner

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**