

1.
N^o 8820

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-28-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

531 X 533

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

YES


WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

Heldy Bannan

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

J. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
N^o 8820

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *March 25*

RECEIVED OF *Kalderhausen* FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Jim Wesner*

TO TAP *Sanitary* SEWER ON THE *South*

OF *Wellman Ave S.E.* AVE. ST. TYPE OF STREET *Hard Surface*

THE PREMISES BEING LOT NO. *9464* HOUSE NO. *533*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Kalderhausen*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**