№ 8825

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-23-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	<u> </u>
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	974 - X C C 7 058
		30000 GO-CD
	Town	· MAIN
SIGNED SIGNED	FILED AT E	ENGINEER'S OFFICE
Inspector for City		···
REMARKS	· .	

№ 8825

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Office 23		
RECEIVED OF Estimated So	one Wichin	rep FEE OF	\$ <u>5</u>
OR WHICH PERMISSION IS GRANTED	ce United Old	wed of Christ	
OTAP Sanutary	SEWER ON THE	Sauth	
F Main and W	AVE. ST. TYPE OF STREET	Hard Luxla	
HE PREMISES BEING LOT NO. 1608		and the second s	
VORK TO BE DONE IN ACCORDANCE WITH ORI		•	IL, AND I
F THE DEPARTMENT OF PUBLIC SERVICE.			
F. 1 - 1	*		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.