

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 8833

DATE INSPECTED

5-15-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

819

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

199' South of Rd 9

WAS LATERAL AT CURB?

Prop YES



WAS ATTACHED TO MAIN

NO

NAME OF CONTRACTOR

M. GORDON SLAGE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

L. L. Patton
Inspector for City

FILED AT ENGINEER'S OFFICE

199'

REMARKS

N^o 8833

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, MAY 16

RECEIVED OF MIKE GEISTENSLAGER FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED GRANT & ALEXANDER

TO TAP SAN SEWER ON THE WEST

OF MILLSTONE LN. N.E. AVE. ST. TYPE OF STREET CHURCH ST.

THE PREMISES BEING LOT NO. 13690, HOUSE NO. 819

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR GEISTENSLAGER

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.