

No 8835

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 5-21-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 806

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

91' NORTH of M.E.
6 1/2'

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR

Holder BAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


N 7

C' of pipe
used to Repair
this

5' 10" walk

16" WATER
LINE

CURB



SIGNED

J. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

91'

REMARKS

Repair
N^o 8835

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *May 20*

RECEIVED OF *Haldichman*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Bonded Pit Co.*

TO TAP *Sanitary*

SEWER ON THE *Northeast corner*

OF *W. 11th St. N.E.*

AVE.

ST. TYPE OF STREET *Hard surface*

THE PREMISES BEING LOT NO. *1186*

HOUSE NO. *806*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldichman*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**