

N^o

8836

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

6-16-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2422

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

69' EAST of MA 8' deep

WAS LATERAL AT CURB?

Prop

Yes

Prop

WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

BEAVER EXCA.


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

S. Latham
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS



N^o 8836

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO,

May 17

RECEIVED OF

Paul Karamby

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

North

OF

Longland Dr. N.E.

AVE.

ST. TYPE OF STREET

Chap. School

THE PREMISES BEING LOT NO.

13591

HOUSE NO.

3422

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

~~Beaver Exca.~~

Beaver EXCA.

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.