

15
N^o 8839

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

6-13-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

719

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

Prop. Yes



WAS ATTACHED TO MAIN

No

NAME OF CONTRACTOR

M. GERSTENSLAGER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

V. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8839

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 10

RECEIVED OF Centerville

FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Shannon & Alexander Co.

TO TAP Sanitary

SEWER ON THE West

OF Milton Lane N.E.

AVE.

ST. TYPE OF STREET City & Sub

THE PREMISES BEING LOT NO. 13654

HOUSE NO. 719

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Centerville

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**