**N**º 8842

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO	DISTANCE FROM FIRST MANHOLE .	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
e de la companya del companya de la companya del companya de la co	No Cutofs	
taling that is a second of the say of	700	
CIONED		
Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

## **№** 8842

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	
RECEIVED OF Reserve Change		
FOR WHICH PERMISSION IS GRANTED 22744	13 Mus Padge	
TO-TAP SENITARY SE		
of	2 h - 2 h	
THE PREMISES BEING LOT NO. 10.053	<i>f</i>	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.