

N^o 8850

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-2-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

9' WEST OF MH 9' DEEP
UP

HOUSE NO. 1898

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB?

No


WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8850

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Aug. 26, 1975*

RECEIVED OF *Haldenbaum* FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED *Amelie Conley*

TO TAP *Sanitary* SEWER ON THE *North*

OF *Massachusetts Ave. S.E.* AVE. ST. TYPE OF STREET *Chp & Lesh*

THE PREMISES BEING LOT NO. *6304 & 6305*, HOUSE NO. *1828*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND IN ACCORDANCE WITH THE ORDINANCES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldenbaum*

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.