

✓
N^o 8853

16
1
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-5-75

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

611

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

WAS LATERAL AT CURB?

Repair

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

Holder Bag M

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Repair

N



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
N^o 8853

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept 2*

RECEIVED OF *Haldichaux*

FEE OF \$ *2.5*

FOR WHICH PERMISSION IS GRANTED *R. Archfield*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Sandy Ave. N.E.*

AVE.

ST. TYPE OF STREET *Chap & Sal*

THE PREMISES BEING LOT NO. *11402*

HOUSE NO. *611*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Haldichaux*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**