## Nº 8861 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-17-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1310	<u> </u>
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT 63 EAS 6 0 F M 19 5 5 5 6  CURB LINE AND DEPTH
WAS LATERAL AT CURB? 45	and the second second
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MALAVITE
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
	N 778
e de la companya de l	4
	11. DEEP
	63
SIGNED William A mm. Inspector for City	FILED AT ENGINEER'S OFFICE
inspector for City	
ECMARKO.	·

Nº 8861

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, 477 15		
RECEIVED OF Malamite	FEE OF \$ 25		
FOR WHICH PERMISSION IS GRANTED HOLD THE	Lucie Bless		
TO TAP Sugar Tour	SEWER ON THE		
of Burd Am 716 AVE. ST.	TYPE OF STREET Chip & Lal		
	, HOUSE NO		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR MAGNITE	· · · · · · · · · · · · · · · · · · ·		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.