FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8863

DATE INSPECTED 10-3-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	**************************************
HOUSE NO. FRIST NATIONAL BANK	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
SIZE OF PIPE USED	CURB LINE AND DEPTH	·
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIANA	& 50W.
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	8'D
V -		= 226° BErd
the state of the s	∂γ̂.	E 100
	05V'U'&	
SIGNED William Harning	FILED AT ENGI	NEER'S OFFICE
* Inspector for City	•	
REMARKS		·

№ 8863

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OF	110, <u>ALA 19 ,</u>		
RECEIVED OF	<i>C I I I I I I I I I I</i>	Level FEE OF \$ 25		
FOR WHICH PERMISSION IS GRANTED	First Vational	Bank !		
TO TAP Santon				
		March Sugar		
13093 -13694-13195 - 13093 THE PREMISES BEING LOT NO. 12-10-10-10-10-10-10-10-10-10-10-10-10-10-				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	t to the second			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.