FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 1720 SIZE OF PIPE USED 4	IF SO HOW AND LOCATION FROM PAINT KNOW US NE MAY 15 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	NAME OF CONTRACTOR BEAVER	
WAS ATTACHED TO MAIN Y 15	NAME OF CONTRACTOR 15 E HV G/4	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	210 13 15 No 13 15 No	
SIGNED William Hann. Inspector for City	FILED AT ENGINEER'S OFFICE	

№ 8868

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, COL. 21
RECEIVED OF Bearing Electric	
FOR WHICH PERMISSION IS GRANTED	Reduced Meets
TO TAP danishary SEWE	
OF MANUEL AND ST. TYPE	OF STREET
THE PREMISES BEING LOT NO. 12.63.443.77	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.