FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO.	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED		
WAS LATERAL AT CURB?	en e	
WAS ATTACHED TO MAIN NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
CANNOT /	EIND SEWER	
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 8873

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Mare, 5
RECEIVED OF 6 ast 30 6 Kcan	eting FEE OF \$ 5.
OR WHICH PERMISSION IS GRANTED Mislau	
OTAP Saulang SEV	WED ON THE Sweeth
F Tumout ano. D. W AVE. TY	PE OF STREET Blackton
HE PREMISES BEING LOT NO. 3/67	
-	. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND I

East 30

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.