№ 8874

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 11-13-75 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM | |
|---|---|--|
| HOUSE NO. 1354 | | |
| SIZE OF PIPE USED. | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 149 EAST OF M 9'D CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? VES | | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| | 91D 12 300 BEAD | |
| SIGNED William Romme Inspector for City | FILED AT ENGINEER'S OFFICE | |
| REMARKS | | |

№ 8874

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

| | MASSILLON, OHIO, More 5 |
|---|-------------------------|
| RECEIVED OF CHIET Executing | FEE OF \$ 25 |
| FOR WHICH PERMISSION IS GRANTED Haise - 11- | ivetare |
| TO TAP Santary SEW | er on the Marth |
| OF Bund au. n. C. AVE. TYP | E OF STREET Chih & Lead |
| THE PREMISES BEING LOT NO. 11752 | , HOUSE NO. 1354 |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE. | |
| NAME OF CONTRACTOR Crest | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.