## $N^{\underline{o}}$ Following data to be answered by inspector and signed when returned

DATE INSPECTED 11-13-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 1366	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED 6	DOWN STREAM TO DITCH AT 260 EAST OF HI 90	
WAS LATERAL AT CURB? VES		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR CREST	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	151	
	4.0	
4	910 181	
	<u> </u>	
De la companya del la companya de la		
SIGNED William Hammer FILED AT ENGINEER'S OFFICE		
Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	· .	

Nº 8875

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, //ov. 5
RECEIVED OF CHILL Exeruster	ing FEE OF \$ $\mathcal{A}$ =
FOR WHICH PERMISSION IS GRANTED Kaisu	Regetone
TO TAP Sanitary SE	
OF Bund am. W.E. ST. TY	PE OF STREET Chip & See
THE PREMISES BEING LOT NO. 11753	HOUSE NO. 1366
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	· .
NAME OF CONTRACTOR Cust	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.