FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-75 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 13 55 DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 14/ EAS OF M4 9'D CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES WAS ATTACHED TO MAIN NAME OF CONTRACTOR CREST
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
34' 16 300BENE
867 91D
SIGNED William Hammer FILED AT ENGINEER'S OFFICE
Inspector for City

№ 8879

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, 1/20. 5
RECEIVED OF Crust Excavely	ing EFF OF S I
FOR WHICH PERMISSION IS GRANTED Raisu-	Reystone
TO TAP Sanctary SEI	WER ON THE South
of Bund and 716 AVE. TY	-
THE PREMISES BEING LOT NO. 11667	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO) N
NAME OF CONTRACTOR Livet	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.