Nº 8880

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-14-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
House No. /345	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 94/ LAST OF 14 9 DEF 15 CURB LINE AND DEPTH
WAS LATERAL AT CURB? VES	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR CRUSST
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
A N	36 V 910
	34/>
SIGNED William Manemanninspector for City	FILED AT ENGINEER'S OFFICE
DELLARIA	
REMARKS	<u> </u>

Nº 8880

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Hov.	5
RECEIVED OF Crust Exame	Ting		FEE OF S 25
FOR WHICH PERMISSION IS GRANTED Mail	Kuptine		
TO TAP Sanctary SE	WER ON THE	outh	
Bend are. W. E. AVE. TV	PE OF STREET	lik & Si	al .
THE PREMISES BEING LOT NO. 11666	, HOUSE NO	134	65
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Liest			
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.