Nº 8881^V

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED DEST 21 16	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2/12 LIVE	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED.	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Husbritum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
121/1	Shut from 5. W carner
Benela 42 feet 26 fee	1 beliend our 20 feet from Building hook of it \$ a feet from & F
·	hook up it \$ a feet from & E
LW B	Car
SIGNED J 47	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

№ 8881

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

9-16-76

	MASSILLON, OHIO,
RECEIVED OF Haldhebau	m FEE OF \$ 25
SA MBO'S FOR WHICH PERMISSION IS GRANTED	Pollerin & & me set to
TO-TAP Saintany	NORTH Just 1
L.W.E. W Wallace and 6	/E. TYPE OF STREET Land Surface
O. 4. 330 THE PREMISES BEING LOT NO.	HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND FOR THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Halduhaume

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.