FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 8885

DATE INSPECTED 12-9-75	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Rear
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	1
N	\$ - \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	D (60)
SIGNED	
Inspector for City	FILED AT ENGINEER'S OFFICE

№ 8885

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

6 ...

	i	5	t	L.	جے ر	5	7
ر	-	/	grann ion	À	57	•-	re

	MASSILLON, OHIO,					
RECEIVED OF Beann & pea	nating Co. FEE OF \$ 5.					
FOR WHICH PERMISSION IS GRANTED						
CUT-OFF Sanitary SE	WER ON THE South					
	PE OF STREET Hard Luxface					
THE PREMISES BEING LOT NO. 290	HOUSE NO. 5/5-1. N. E					
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F OF THE DEPARTMENT OF PUBLIC SERVICE.						
NAME OF CONTRACTOR Beance						

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.