

N^o 8889

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-11-76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2048

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

8' EAST OF MA 8' DEEP

WAS LATERAL AT CURB?

Prop.

Yes

Prop

WAS ATTACHED TO MAIN


NO

NAME OF CONTRACTOR

G. MALAVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED

V. Nathan
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 8889

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, DEC. 10

RECEIVED OF GRANITE BROS. FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED MALIVITE

TO TAP SANIT SEWER ON THE N.W.

OF 1264 WOOD CIR N.E. AVE. ST. TYPE OF STREET Alley

THE PREMISES BEING LOT NO. 13732, HOUSE NO. 2045

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MALIVITE

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.