

N^o 8897

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 4-2-76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 938

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

174' SOUTH OF FH 9' DEEP

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

MA/AVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N →



SIGNED

William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8897

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Jan. 6*

RECEIVED OF

Gring Bros.

FEE OF \$

2.50

FOR WHICH PERMISSION IS GRANTED

Gring Bros.

TO TAP

Sanitary

SEWER ON THE

East

OF

Calhoun St. 71.8'

AVE.

ST. TYPE OF STREET

City & School

THE PREMISES BEING LOT NO.

13747

HOUSE NO.

938

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Melanite

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**