Nº 8899

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 1-20-7C	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 5-06	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
SIZE OF PIPE USED	CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	L OF BUILDING SERVED.	
	56'	
W == 7		
10 /		
SIGNED	FILED AT ENGINEER'S OFFICE	
Inspector for City		
REMARKS		
VENNUVO		

№ 8899

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

. MA	SSILLON, OHIO, Jane. 16	
RECEIVED OF Just A. Justini	10 G. FEE OF \$ 5.	
FOR WHICH PERMISSION IS GRANTED PRINCIL	Crawn Stil Co	
CUT. OF F- LAW SEWER	ON THE	
OF 3 we file AVE. TYPE OF	OF STREET Had furface	
THE PREMISES BEING LOT NO. 2890	ye.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR Julian	*	
$\mathcal{L}_{\mathcal{L}}$		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.