

Nº 8908

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Cannot find Sewer

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

CUT-OFF

N^o 8908

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

292' 336

MASSILLON, OHIO, Jan. 23

RECEIVED OF

Beane Excavating Co.

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

St. Paul Lutheran Church

CUT-OFF
TO-TAP

Sanitary

SEWER ON THE

South

OF

Harvard Ave NE

AVE.

ST. TYPE OF STREET

Wig & Lel

THE PREMISES BEING LOT NO.

721

HOUSE NO.

129

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beane

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.