

N^o 8909FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
SIZE OF PIPE USED _____ CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED _____ FILED AT ENGINEER'S OFFICE _____
Inspector for City

REMARKS _____

REPAIR

Nº 8909

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Jan. 29

RECEIVED OF

A. J. Williams, Inc.

FEE OF \$ 2.50

FOR WHICH PERMISSION IS GRANTED

Richard M. Adair

TO TAP

Sanitary

SEWER ON THE

West

OF

9th St. W. E.

AVE.

ST. TYPE OF STREET

Chippewa St.

THE PREMISES BEING LOT NO.

5286

HOUSE NO.

879

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Dianna

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**